

Plant and Equipment Wellness Training Course Workbook and Reference Materials

CONTENTS

Extracts on the Causes of Equipment Failure	2
Activity 1 – Simple Reliability Block Calculations	3
Case Study 1 – Shaft Quality Control for Bearing Reliability	4
Activity – Put 3T Quality Control in Maintenance Procedures	6
Description of Process 1 – Risk Identification	11
Activity 2 – Costing Failure Consequences	12
Activity 3 – Constructing an Equipment Process Map	18
ACE 3T Standard Operating Procedure <i>Example</i>	21
Activity 3 continued – Constructing a Job Process Map	24
Description of Process 2 – Determine the Risk Rating	25
Activity 4 – Risk Rating	26
Activity 5 – Equipment Criticality	27
Risk Identification and Analysis - Template 1	28
Risk Treatment Schedule and Action Plan - Template 2	29
Risk Assessment Matrix	31
Description of Process 3 – Selecting Risk Control Strategy	32
Activity 6 – FMEA System Level	33
Activity 6 continued – FMEA Component Level	35
Activity 7 – Operating and Maintenance Strategy Selection	37
Activity 7 continued – Determine Remaining Risk	39
Description of Process 4 – Introducing Risk Controls	41
Activity 8 – Write an ACE 3T Procedure	42
Description of Process 5 – Risk Monitoring and Measuring	45
Activity 9 – Case Study of Maintenance History Analysis and Weibull Plot	46
Description of Process 6 – Continual Improvement	48
Activity 10 – Reliability Growth Cause Analysis	49
5 Whys Method of Root Cause Analysis	54
Activity 11 – 5 Why Analysis of Compressor Failure	56
Activity 12 – Plan of Action	61
Example 1 of ACE 3T Standard Operating Procedure (Flange)	63
Example 2 of ACE 3T Procedure (Conveyor Pulley)	66