

Predictive Maintenance Program Training Course Workbook and Reference Materials

CONTENTS

Extracts on the Causes of Equipment Failure	2
Activity 1 – Bending and Torsional Stress in Steel Parts	3
Activity 3 – FMEA System Level.....	4
Activity 3 (alternative) – FMEA Component Level	6
Activity – Equipment Criticality	8
Risk Assessment Matrix.....	11
Risk Identification and Analysis – Template 1	12
Risk Treatment Schedule and Action Plan – Template 2	13
Activity – CIP Circuit Criticality	14
Activity 4 – CIP Circuit Maintenance Strategy Selection	16
Activity 5 – Develop CIP Supply Pump Predictive/Preventive Maintenance Strategy.....	17
Activity 7 – Confirm Operating and Maintenance Strategy Selection do Reduce Operating Risk ...	18
Activity 8 – Improve Procedures with Inspection and Test Plan Standards	20
Proposals for Shaft Alignment Tolerances.	23
Bearing Health in Highly Reliable Machines	27
Selecting Reliability Standards for Pump Set Equipment	29
Downtime and Failure Costing Spreadsheets	31